Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

CLIENT INFORMATION

Client ID:

Client Name:

Alt. Client ID: 16016SW-1033

Address:

AGENCY INFORMATION

Agency: SWHRA

Address: 1574 White AVE

Henderson, TN

Agency Phone: (731) 989-5111

Fax:

Email Address:

Agency Contact: Oliver, Jerry

Work Phone: Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-424-9310

Client Name: Client ID:

Alt. Client ID: 16016SW-1033

Work Order (Bid Form)

Work Order Name

Report Run On: 5/14/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 6

Measures

Measure 1	Add window screens to W1,W2,W3,W4,S2 and E2			Componen	ts		I.	nspected
Comment								
				Estimated			Actual	
# Material/Lab	oor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Unspecified	Misc Material	Each	1					
2 Labor	Labor	Hour					Target Hand	
Other Detail				,	1. 111 111 111	ALLES LANGE LA SERVICE STORY,		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	F18071. 3.107. 71.207.			

Client Name:

Client ID:

Alt. Client ID: 16016SW-1033

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/14/2010

DOE Weatherization Assistant

Version 8.5.0 Page 2 of 6

	Measure 2 Infilt	ration Redctn			Componen	nts			Inspecte
C	omment .				Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal electric furnace in bath room, holes in wall and pipe penetrations and corners	Each	1					
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Seal door jams form hall to all bedrooms, Seal pipep under kitchen sink	Each	1		(Manageria)			
4	Labor	labor	Hour		Company of the Compan				
5	Construction Materials/Hardwar e	Laundry room seal pipe penetrations behind washer, Seal breaker box, Seal door jam, Seal pipe penetrations for water heater and exhaust	Each	1					
6	Labor	Labor	Hour						
7	Construction Materials/Hardwar e	Bath seal pipes under vanity, D1 weaather-strip	Each	1					
8	Labor	Labor	Hour		The state of the s				
2	ther Detail			¬ [; [
				J L		***************************************			
L				Moscur	e Sub Total:			Sub Total:	
Γ	Field Notes:				Į.		······		

Client Name: Client ID:

Measure 3 Repl	ace Htg. System			Componen	ts H1		i	Inspecte
Comment Remove	old vented space heater	and seal	flu.					
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Heating Equipment	Direct Vent 35-40 KBTU Natural gas Heater	Each	1					
2 Labor	Labor	Each	1					
Other Detail			1			1		
			Measur	e Sub Total:			Sub Total:	
	Monitor is Needed			Componen				Inspecte
Comment		Units	***************************************	Estimated			Actual	
Comment # Material / Labor	Monitor is Needed Description / Comment CO monitor	<i>Units</i> Each	Qty 1	-		Qty		Inspecte Total
Comment * Material / Labor ! Health and Safety ! Items	Description / Comment		Qty	Estimated		Qty	Actual	
# Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each	Qty 1	Estimated		Qty	Actual	
# Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each	Qty 1	Estimated		Qty	Actual	
# Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each	Qty 1	Estimated		Qty	Actual	
# Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated			Actual	
Comment # Material / Labor 1 Health and Safety	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
Comment # Material / Labor 1 Health and Safety Items 2 Labor Other Detail	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

Client Name: Client ID:

Alt. Client ID: 16016SW-1033

Work Order Name:

Report Run On: 5/14/2010

	Any Other Heating Syst	tem Proble	em	Component	's		I	nspected
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Repair electric heater	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						, (
			Measur	e Sub Total:] .	Sub Total:	
	ssureRelief Piping Nee	ded		Componen				Inspected
	ssureRelief Piping Nee			Estimated			Actual	
Comment # Material / Labor	Description / Comment	Units	Qty	-		Qty		Inspected Total
Comment # Material / Labor	Description / Comment		Qty 1	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items	Description / Comment	Units		Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items	Description / Comment Pressure relief piping	<i>Units</i> Each	1	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	1	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	1	Estimated Unit Cost			Actual Unit Cost	
Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	1	Estimated			Actual	

i	Measure 7 Smo	ke Detector is Needed			Componen	ts		li	nspected
C	omment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Smoke detector	Each	1					
	Items		,						
2	Labor	Labor	Hour	1					
C	Other Detail						-		
				Measur	e Sub Total: [Sub Total:	
	Field Notes:							- ALABATVA	
							,		
		***************************************	144 1 0				Cran	nd Total:	
			Work O	rder Gra	nd Total:		Gran	u ivial.	

Client Name: Client ID:

Alt. Client ID: 16016SW-1033

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/14/2010

DOE Weatherization Assistant Version 8.5.0

Page 6 of 6